
From: David Craymer (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=DAVID09]
Sent: 5/13/2015 1:42:36 PM
To: Daniel L Siegfried (Services - 6) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=DANI66213c]; Cathy C Taylor (Services - 6) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Cathy25]; Kenneth Roller (Services - 6) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Kenne64]
CC: Doug Wight (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Dougl7]; John Cima (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=John171]; Jeffrey C Heffelman (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Jeffre3]; Jeffrey R Marcell (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Jeff136]; Clay T Burns (Services - 6) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Clay006]
Subject: FW: Ash Pond ABC inspection 05/13/15
Attachments: 20150513091936491.pdf; ATT00001.htm

Redacted

Dave Craymer

804-273-3685 (W)

804-839-2791 (C)

From: Jeffrey C Heffelman (Generation - 3)
Sent: Wednesday, May 13, 2015 12:41 PM
To: Ed Baine (Generation - 3); David Craymer (Generation - 34)
Subject: Fwd: Ash Pond ABC inspection 05/13/15

FYI

Sent from my iPhone

Begin forwarded message:

00013091

From: "Jeffrey R Marcell (Generation - 3)" <jeffrey.r.marcell@dom.com>
Date: May 13, 2015 at 11:42:36 AM EDT
To: "Michael J Winters (Generation - 34)" <Michael.J.Winters@dom.com>
Cc: "John Cima (Generation - 34)" <john.cima@dom.com>, "Jeffrey C Heffelman (Generation - 3)" <Jeffrey.C.Heffelman@dom.com>, "Kenneth Roller (Services - 6)" <kenneth.roller@dom.com>
Subject: RE: Ash Pond ABC inspection 05/13/15

Attached.

No Discharge at C Pond. Standing water around weir and Southeastern edge of Pond C and into center of C Pond beginning to recede. Water level inside bottom of weir is below pipe.

Very little to no seeping and dripping inside C Pond discharge weir about.

Standing water behind sand-bags at 'A' with standing water at the toe of the slope and flow under bags into rip-rap. The southern edge of the 'A' pond interior, from the SE corner to the sandbags, continues to hold water. The NE end of A Pond is holding water in pathway created from matting/equipment activity, noticeable depression in this section from activity related to drilling.

No standing water behind sand-bags at 'B' pond.

Precipitation on 05/11 was 0.19".

Let me know if you have any questions.

Jeff Marcell

Environmental Supervisor

Possum Point Power Station

Ladysmith & Remington CT Sites

703-441-3813 (phone)

8-795-3813 (tie)

703-441-3897 (fax)